

BRS Save #133



While towing a hang glider with instructor and student on board, the Dragonfly tug ultralight suffered a failed component, which locked the horizontal stabilizer. A normal landing was not going to be possible.

“A tang supporting the cable bracing for the tail broke causing the horizontal to drop. There was no travel at all in the elevator! Since I wasn't in immediate trouble I waited till I was in a better area and fired the BRS. Thanks for the wonderful product!”

Result: Pilot survived!