

BRS Save #170-171



“Deployed the chute while the aircraft was pointing the ground at a steep angle and at a rapidly increasing speed. The aircraft started to swing and stabilized rather quickly. Then it landed at the side of a hill at angle of approximately 30 degrees.

No injuries occurred. Not a simple scratch, apart from the psychological part of event.