

BRS Save #113



On approach for landing, the Titan Tornado pilot struck hard-to-see power lines. As the ultralight passed through the lines, it pitched forward. The pilot quickly deployed which pulled the nose up and the aircraft hit the ground flat and lost its forward speed.

“Even though the parachute didn't have enough altitude (only 25 feet) to fully open, it arrested my forward movement and repositioned the aircraft. I suffered injuries but will heal. My next aircraft will definitely have a BRS.”

Result: Pilot Survived!